APPENDIX A

FLIGHT PAYLOAD STANDARDIZED HAZARD CONTROL REPORT FOR THE AMS-02

				A. N	JMBER	B. PHAS	SE	C. DATE		
	FLIGHT PAYLOAD STANDARDIZED HAZARD CONTROL REPORT				AMS-02-1	Phase 0/I		January 16, 2001		
D. PAYLOAD, DTO, DSO or RME (Include Part Number(s), if applicable)					AZARD TITLE E. VEHICLE					
Alpha Magnetic Spectrometer-02 (AMS-02) (See attached list of hardware)					STANDARD HAZAR	DS	Shuttle/Station	1		
F.	DESCRIPTION OF HAZARD:	G.	HAZARD CONTROLS: (complies with)	H. APP.	I. VERIFICATION	METHOD,	REFERENCE	AND STATUS:		
1.	Structural Failure (payloads must comply with the listed requirements for all phases of flight)	a) b)	Designed to meet the standard modular locker stowage requirements of NSTS 21000-IDD-MDK or equivalent IDD, or Stowed in SPACEHAB per MDC91W5023. Note: Locker and Soft Stowage items only		N/A; See Unique Hazard AMS-02 hardware.	l Report #AM	1S-02-1 for hazard	d control of structural failure of		
2.	Structural Failure of Sealed or Vented Containers	a)	Sealed containers must meet the criteria of NASA- STD-5003, contain a substance which is not a catastrophic hazard if released, be made of conventional metals, and have a maximum delta pressure of 1.5 atm.		a) N/A; The AMS-02 does not have any sealed containers.					
		b)	For intentionally vented containers, vents are sized to maintain a 1.4 factor of safety for Shuttle or a 1.5 factor of safety for Station with respect to pressure loads.	⊠	Also, making the TOF a container. The different containers during ascent systems. Verification of	nd Si Tracker ial pressures and descent the proper fa drawings and	assemblies light the between the inside will be minimized actors of safety will			
3.	Sharp Edges	Mee	ets the intent of one or more of the following:							
		a)	NASA-STD-3000 / SSP 50005							
		b)	SLP 2104							
		c)	NSTS 07700 Vol. XIV App. 7 (EVA hardware)		c) Verification by sharp	by sharp edge inspections of exposed edges, corners or protrusion				
		d)	NSTS 07700 Vol. XIV App. 9 (IVA hardware) / SSP 57000		AMS-02 hardware. Status: Open. d) Verification by sharp edge inspections of exposed edges, corners or protrusions of AMS-02 hardware. Status: Open.					

				A. N	JMBER	B. PHAS	SE	C. DATE
FLIGHT PAYLOAD STANDARDIZED HAZARD CONTROL REPORT				STD- AMS-02-1		Phase 0/I		January 16, 2001
D. PAYLOAD, DTO, DSO or RME (Include Part Number(s), if applicable)					RD TITLE		E. VEHICLE	
Alı	oha Magnetic Spectrometer-0	2 (A	MS-02) (See attached list of hardware)		STANDARD HAZAR	DS	Shuttle/Station	
F.	DESCRIPTION OF HAZARD:	G.	HAZARD CONTROLS: (complies with)	H. APP.	I. VERIFICATION	,		
4.	Shatterable Material Release	a) b)	All materials are contained. Optical glass (i.e. lenses, filters, etc.) components of crew cabin experiment hardware that are non-stressed (no delta pressure) and have passed both a vibration test at flight levels and a post-test visual inspection. Payload bay hardware shatterable material components that weigh less than 0.25 lb and are non-stressed (no delta pressure) or non-structural.		in the PMT housings if b	oroken. Verifi on of flight had glass, but it wen. Verification	ication by review of rdware conformanc will have a plexiglas on by review of the	e to drawings. Status: Open. ss cover to protect it and ACOP drawings and
5.	Flammable Materials	a) b)	A-rated materials selected from MAPTIS, or Flammability assessment per NSTS 22648	⊠ ⊠	of drawings and inspecti materials certification fro Open. b) (Applicable for non-lists, assessment of draw	ion of AMS-0: om EM2/Mate JSC built hard vings and insp	2 hardware. Verificerials and Processes ware) Verification ection of AMS-02 I	eview of materials lists, review cation will be completed by a Technology Branch. Status: by assessment of materials nardware. Verification will be and Processes Technology
6.	Materials Offgassing	a)	Offgassing tests of assembled article per NASA-STD-6001		02 materials.	•		control of offgassing of AMS-
7. 7.1	Nonionizing Radiation Non-transmitters	a) b)	Pass NSTS 21288 / SSP 30237 EMI compatibility testing, or NSTS/MS2 approved analysis		a) EMI tests will be per be by NASA approval of Status: Open.			MS-02. Final verification will S 21288 and SSP 30237.

	A. NU	JMBER	B. PHAS	BE	C. DATE				
FLIGHT PAYLOAD STANDARDIZED HAZARD CONTROL REPORT				hase 0/I	January 16, 2001				
D. PAYLOAD, DTO, DSO or RME (Include Part Number(s), if applicable)				HAZARD TITLE E. VEHICLE					
Alpha Magnetic Spectrometer-02 (AMS-02) (See attached list of hardware)				STANDARD HAZARDS Shuttle/Station					
G. HAZARD CONTROLS: (complies with)	H. APP.				E AND STATUS:				
Beams are totally contained at the maximum possible power and there is no crew access, or									
b) Meet ANSI Z136.1-1993 for class 1, 2, or 3a Lasers (as measured at the source).									
Pass acceptance tests which include open circuit & loaded voltage measurements, visual examination, and leakage check under vacuum (e.g. 6 hours at 0.1 psia). Note: Above acceptance testing for button cells in Section 8.2 which are soldered to a circuit board in commercial equipment (not applicable to those button cells in a spring-loaded clip) is limited to a functional check of the equipment utilizing the subject battery.		The ACOP single board computer will contain a small battery, which will be a maintain time synchronization and bios parameters. Specifications for this bat TBD, since the specific board has not yet been selected. Verification of hazar will be by functional check, visual examination and leakage check under vacual Status: Open.							
a) Meets IVA touch temperature criteria of letter, MA2- 95-048. b) Meets EVA touch temperature criteria of NSTS 07700 Vol. XIV App. 7.		a) Verification of comp analyses and/or testing.b) Verification of comp	liance with Na Status: Open.	ASA Letter #MA	A2-95-048 will be by thermal				
	REPORT or RME (Include Part Number(s), if applicable) 2 (AMS-02) (See attached list of hardware) G. HAZARD CONTROLS: (complies with) a) Beams are totally contained at the maximum possible power and there is no crew access, or b) Meet ANSI Z136.1-1993 for class 1, 2, or 3a Lasers (as measured at the source). Pass acceptance tests which include open circuit & loaded voltage measurements, visual examination, and leakage check under vacuum (e.g. 6 hours at 0.1 psia). Note: Above acceptance testing for button cells in Section 8.2 which are soldered to a circuit board in commercial equipment (not applicable to those button cells in a spring-loaded clip) is limited to a functional check of the equipment utilizing the subject battery.	ATANDARDIZED HAZARD CONTROL REPORT For RME (Include Part Number(s), if applicable) 2 (AMS-02) (See attached list of hardware) G. HAZARD CONTROLS: (complies with) APP. a) Beams are totally contained at the maximum possible power and there is no crew access, or b) Meet ANSI Z136.1-1993 for class 1, 2, or 3a Lasers (as measured at the source). Pass acceptance tests which include open circuit & loaded voltage measurements, visual examination, and leakage check under vacuum (e.g. 6 hours at 0.1 psia). Note: Above acceptance testing for button cells in Section 8.2 which are soldered to a circuit board in commercial equipment (not applicable to those button cells in a spring-loaded clip) is limited to a functional check of the equipment utilizing the subject battery.	Pass acceptance tests which include open circuit & loaded voltage measurements, visual examination, and leakage check under vacuum (e.g. 6 hours at 0.1 psia). Note: Above acceptance testing for button cells in a spring-loaded clip) is limited to a functional check of the equipment utilizing the subject battery. Application and scheme Note: Application and scheme Note: Application of companalyses and/or testing.	TANDARDIZED HAZARD CONTROL REPORT IT RME (Include Part Number(s), if applicable) 2 (AMS-02) (See attached list of hardware) 3 (AMS-02) (See attached list of hardware) 4 (APP) 3 (APP) 3 (APP) 4 (APP) 4 (APP) 5 (ASS-02) (See attached list of hardware) 5 (AMS-02) (See attached list of hardware) 5 (AMS-02) (See attached list of hardware) 5 (AMS-02) (See attached list of hardware) 6 (AASARD CONTROLS: (Complies with) 6 (APP) 8 (ASS-02 lasers are in the reflown/series elements and will be added voltage measurements, visual examination, and leakage check under vacuum (e.g. 6 hours at 0.1 psia). Note: Above acceptance testing for button cells in Section 8.2 which are soldered to a circuit board in commercial equipment (not applicable to those button cells in a spring-loaded clip) is limited to a functional check of the equipment utilizing the subject battery. 8 (ASS-02) 8 (AMS-02) (See attached list of hardware) 8 (ANS-02) (See attached list of hardware) 9 (ANS-02) (See attached list of hardware) 1 (ANS-02) (ANS-02) (See attached list of hardware) 1 (ANS-02) (See attached list of hardware) 1 (ANS-02) (See attached list of hardware)	TRANDARDIZED HAZARD CONTROL REPORT or RME (Include Part Number(s), if applicable) 2 (AMS-02) (See attached list of hardware) G. HAZARD CONTROLS: (complies with) APP. a) Beams are totally contained at the maximum possible power and there is no crew access, or (as measured at the source). Pass acceptance tests which include open circuit & loaded voltage measurements, visual examination, and leakage check under vacuum (e.g. 6 hours at 0.1 psia). Note: Above acceptance testing for button cells in Section 8.2 which are soldered to a circuit board in commercial equipment (not applicable to those button cells in a spring-loaded clip) is limited to a functional check of the equipment utilizing the subject battery. The ACOP single board computer will contain a small maintain time synchronization and bios parameters. S TBD, since the specific board has not yet been selected will be by functional check, visual examination and le Status: Open. Note: Application and schematic reviewed and approved by, a Note: Application and schematic reviewed and approved by, analyses and/or testing. Status: Open. Note: Application of compliance with NASA Letter #M/analyses and/or testing. Status: Open.				

		A. N	JMBER	B. PHAS	BE	C. DATE		
FLIGHT PAYLOAD S	TANDARDIZED HAZARD CONTROL REPORT	STD-	AMS-02-1 Phase 0/I		hase 0/I	January 16, 2001		
D. PAYLOAD, DTO, DSO or RME (Include Part Number(s), if applicable) Alpha Magnetic Spectrometer-02 (AMS-02) (See attached list of hardware)			HAZARD TITLE STANDARD HAZARDS E. VEHICLE Shuttle/Station					
F. DESCRIPTION OF HAZARD:	G. HAZARD CONTROLS: (complies with)	H. APP.	I. VERIFICATION	METHOD,	REFERENCE	AND STATUS:		
10. Electrical Power Distribution	Shuttle payload - Meets all circuit protection requirements of Letter TA-92-038. Station payload - Meets station interface circuit protection requirements of SSP 57000 and payload circuit protection requirements of Letter TA-92-038.		a & b) Verification by review of AMS-02 and ACOP power distribution drawings. Status: Open; See AMS-02 and ACOP preliminary power distribution schematics. [NOTE: Schematics were too large for this document, please find as separate submittals. (Figures 5.11.1 and 5.13.5)]					
11. Ignition of Flammable Atmospheres in Payload Bay	All ignition sources are controlled as required in Letter NS2/81-MO82, and MLI grounded per ICD 2-19001.	⊠	solenoid which will ope	n a He Vent V ources will be of drawings, a grounded per	Valve during launch controlled per lett and inspection of har ICD 2-19001. Ve	erification by review of		

		A. N	UMBER	B. PHAS	SE	C. DATE	
FLIGHT PAYLOAD	STD- AMS-02-1		Phase 0/I		January 16, 2001		
D. PAYLOAD, DTO, DSC	HAZARD TITLE E. VEHICLE						
Alpha Magnetic Spectromete	r-02 (AMS-02) (See attached list of hardware)		STANDARD HAZAR	DS	Shuttle/Station	n	
F. DESCRIPTION OF HAZARD:	G. HAZARD CONTROLS: (complies with)	H. APP.	I. VERIFICATION	METHOD,	REFERENCE	AND STATUS:	
12. Rotating Equipment	Rotating equipment meets criteria of NASA-STD-5003 for obvious containment.						

			A. N	UMBER	B. PHAS	SE	C. DATE
FLIGHT PAYLOAD STANDARDIZED HAZARD CONTROL REPORT				AMS-02-1	Phase 0/I		January 16, 2001
D. PAYLOAD	, DTO, DSO o	or RME (Include Part Number(s), if applicable)	HAZA	RD TITLE		E. VEHICLE	
Alpha Magnetic	Spectrometer-0	2 (AMS-02) (See attached list of hardware)		STANDARD HAZAR	DS	Shuttle/Statio	n
F. DESCRIPT HAZARD:	TION OF	G. HAZARD CONTROLS: (complies with)	H. APP.	I. VERIFICATION	METHOD,	REFERENCE	AND STATUS:
Mating/dematiconnectors 14. Contingency Fragid Safing		a) Shuttle payload - Meets all rapid safing requirements of Letter MA2-96-190. b) Station payload - Meets rapid safing requirements of Letter MA2-96-190, and design shall not impede emergency IVA egress to the remaining adjacent pressurized volumes.		will be mounted on an ir Assembly, and will be E be available for continge for safety) in the event of connectors (less than 32 for mission success (not mating/demating of these Verification will be by a certification of flight hard to ensure note for remove mating/demating. Verification of proper mature.	nterface panel EVA accessible oncy EVA manual fissible bus fail Video will be required for see connectors a mate/demate redware conforming power from the properties of the content of the properties of the content of	on the USS-02, 1 e. The redundant ting/demating for ure or an AMS-0 available for corsafety) in the ever will comply with assessment, revirance to drawing om the 120 V dc of ACOP HDs will	-
APPROVAL		PAYLOAD ORGANIZATION	<u> </u>			SSP/ISS	
PHASE I	ORIC	SINAL SIGNED BY JAMES R. BATES ON 1/17/01		ORIGINAL	SIGNED B	Y AXEL M. L.	ARSEN ON 1/17/01
PHASE II							
PHASE III							

AMS-02 Hardware Covered by Hazard Report #STD-AMS-02-1:

Cryogenic Superconducting Magnet (Cryomag)

Unique Support Structure-02 (USS-02) (which includes the vacuum case for the cryomag)

Synchrotron Radiation Detector (SRD)

Transition Radiation Detector (TRD)

Time-Of-Flight (TOF) Scintillator Assemblies

Ring Imaging Cherenkov Counter (RICH)

Electromagnetic Calorimeter (ECAL)

Data and Interface Electronics

Electrical Cables


Two Monitoring and Control Computers (MCCs)

Power Distribution Box

AMS Crew Operations Post (ACOP)


Passive Payload Attach System (PAS)

Meteoroid and Orbital Debris (MOD) Shields




ACOP Drawer Fan

Rear View



Fan assembly Rear connectors to interface to the Express Rack

ACOP Drawer (rear view) (updated)



ACOP Drawer (front view) (updated)